



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-15-96 / BATTERY CHARGING - RECEIVING DOCK	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	No visible unit label. Fan does not run. Belt is tight.
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Fan total pressure recorded.	No
Is Fan interlocked with any other asset? if so, list:	NA
When is fan used (application) and any specific time?	NA
Make, Model, and Serial Number:	Motor: marathon 1/6HP 115V 3.6A 1725 RPM
Fan CFM:	0