



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-37-93 L5 OVEN EXHAUST STACKS	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	Clean out panels not fully attached
<ul style="list-style-type: none"> • Open File.jpg 	
Make, Model, and Serial Number:	Unit data: NYB K10078-105 12 PLR MOTOR 3hp 460 4.5a
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Fan CFM:	Vel: 1549 10" Cfm:852
Fan total pressure recorded.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Is Fan interlocked with any other asset? if so, list:	L5 oven
When is fan used (application) and any specific time?	L5 oven