



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-24-96 / L6 OVEN	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	Missing discharge panel cover Suction panel cover is not fully secured. Tried to place but is stuck in current position
<ul style="list-style-type: none"> Open File(1).jpg Open File.jpg 	
Make, Model, and Serial Number:	Unit data: NYB SHOP NUMBER:F00195-100 MN 18PLR Motor: 7.5HP 460 6.5 A
Attach picture of asset.	Yes
<ul style="list-style-type: none"> Open File.jpg 	
Fan CFM:	Vel: 554 16" round Cfm:773
Fan total pressure recorded.	Yes
<ul style="list-style-type: none"> Open File.jpg 	
Is Fan interlocked with any other asset? if so, list:	L6 oven
When is fan used (application) and any specific time?	L6 oven