



## Nestle (Mt Sterling, KY)

### CheckList Information

<b>Name :</b>	MAU-7-96 / L6&8 OVEN AREAS	<b>Status :</b>	NotSubmitted
<b>Assigned Organization :</b>	National TAB	<b>Asset :</b>	
<b>Requesting Organization :</b>	National TAB		

### CheckList Item Details

**MAU**

Observe unit to ensure operational & no visual issue. If any comment. Note # of Duct Drops.	NO VISUAL ISSUES
Unit Has Exhaust\Relief Fans & How Many. Note N/A if this does not apply.	N/A
Verify outside air damper position & note approximate open amount (visual). Attached Picture	DAMPER OPENS
No Relief/Exhaust in Operation @ Time of Testing. Note "N/A" if this system does not have Relief/Exhaust	N/A
Fan Total Pressure Recorded	YES
Fan VFD Speed (HZ)	N/A
OA Damper Position (Controls Output) include picture of damper position.	DAMPER OPENS
Attach picture of each asset	Yes

**Unit Operation**

Heating	No
Cooling	No
Wash-Down Validation	NOT APPLICABLE
Make, Model, and Serial Number:	NL, NL, 9802288-01
Fan CFM:	6,302CFM