



Nestle (Mt Sterling, KY)

CheckList Information

Name :	RMAU-9 Mix Room North	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

OBSERVE UNIT TO ENSURE OPERATIONAL & NO VISUAL ISSUE. IF ANY COMMENT . NOTE # OF SUPPLY & RETURN DUCTS	2 supply and 2 returns
<ul style="list-style-type: none"> • Open File.jpg 	
VERIFY OA DAMPER POSITION & NOTE APPROXIMATE OPEN AMOUNT(VISUAL). ATTATCH PICTURE	Closed
DOES UNIT HAVE EXHAUST/RELIEF FANS AND HOW MANY	Yes, 4 relief fans
NO RELIEF/ EXHAUST FANS OPERATIONAL WHEN TESTING	Yes
FAN TOTAL PRESSURE RECORDED	Yes
FAN VFD SPEED	No
<ul style="list-style-type: none"> • Open File.jpg 	
OA DAMPER POSITION(CONTROLS OUTPUT)	Yes