Comfort. Under control.

Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-3-14 / PROCESS MEZZ	**Status :**	NotSubmitted
Assigned Organization :	National TAB	**Asset :**	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	
Attach picture of asset.	
Fan total pressure recorded.	
Is Fan interlocked with any other asset? if so, list:	
When is fan used (application) and any specific time?	
Make, Model, and Serial Number:	
Fan CFM:	