

CheckList List

- WALGREENS SURVEY - EXTERIOR PICTURES
- WALGREENS SURVEY - INTERIOR PICTURES



08-26-24 WALGREENS #17205 BALTIMORE, MD (SURVEY)

CheckList Information

Name : WALGREENS SURVEY - EXTERIOR PICTURES **Status :** Not Completed
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB
Created Date : 08/22/2024 - Brianna Biggs - National TAB

CheckList Item Details

Take picture of front of building.

Comment:

Picture of back of building.

Comment:

Pictures of left & right side of building.

Comment:

Picture(s) of overall roof layout.

Comment:



08-26-24 WALGREENS #17205 BALTIMORE, MD (SURVEY)

CheckList Information

Name : WALGREENS SURVEY - INTERIOR PICTURES **Status :** Completed
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB
Created Date : 08/22/2024 - Brianna Biggs - National TAB
Completed Date : 08/28/2024 - David Annan - National TAB

CheckList Item Details

Interior retail space.

Comment:




08/28/2024



08/28/2024

Office area.

Comment:



08/28/2024

Picture of thermostat RTU1, RTU2, RTU3. List manufacturer/model number if available.

Comment:



08/28/2024



08/28/2024

Picture of thermostat RTU4, RTU5, RTU6. List manufacturer/model number if available.

Comment:

Picture of thermostat RTU7. List manufacturer/model number if available.

Comment:

Stock room / storage area.

Comment:



08/28/2024



08/28/2024

Employee breakroom (if applicable).

Comment:

Any above ceiling pictures that would provide insight to the team (ie RTU drops, issues, etc).

Comment:

All duct work is neatly still intacted

Additional above ceiling pictures & explanation if needed.

Comment:

Ceiling of vestibule (if applicable).

Comment:

Fire panel (if exists). Take picture of front of panel. If able to open panel door easily, take a picture of inside panel. List manufacturer/model number of panel if available.

Comment:

The fire panel is shared with the entire strip mall there is no access.