



Arbys
Paola, KS



RTU-1
Dining



RTU-2
Kitchen



EF-1
Fryer



EF-1



EF-1
Hinge broken, not secured



HD-1
Fryer



HD-1
Filters



EF-2
HD-2 Oven




EF-2



EF-2
No hinge, not secured



HD-2
Oven



EF-3

RR exhaust not operational.