



Culvers
Angola, IN



Thermostats



Rooftop Layout




RTU-1
Dining



RTU-1
Unit label



RTU-2
Kitchen



RTU-2
Unit label



RTU-2
Cookline diffusers perforated.



RTU-2
Cool line diffuser installation correct




Captive Air Hood HMI



HD-1
Griddle



PRV-2
HD-1 griddle



PRV-2




PRV-2
Grease duct



HD-2



PRV-3
HD-2 Fryer



PRV-3




PRV-3



PRV-3
Dent in fan housing.



PRV-1
Restrooms



PRV-1



PRV-1
Backdraft damper installed and able
To move freely.



EF-1



EF-1