

CheckList List

- WALGREENS SURVEY - RTU # 1



09/10/2024

List model serial number & manufacturer.

Comment:

Unit information was not available

Left side of cabinet.

Comment:



09/10/2024

Right side of cabinet.

Comment:



09/10/2024

Front side of cabinet.

Comment:



09/10/2024

Back side of cabinet.

Comment:




09/10/2024

Inside of electrical cabinet.

Comment:




09/10/2024




09/10/2024

Electrical schematic.

Comment:



09/10/2024



09/10/2024

Close up picture of condensing coil.

Comment:



09/10/2024



09/10/2024

Blower compartment.

Comment:



09/10/2024

Mixed air compartment.


Comment:



09/10/2024

Close up of evaporative coil.

Comment:



09/10/2024

Return drop looking down from unit if possible.

Comment:



09/10/2024

Supply drop looking down from unit if possible.

Comment:



09/10/2024

List any visual damage and take additional pictures if needed.

Comment:

No hail guards installed. Unit is not running.
