



CERTIFICATION

PROJECT: Charlotte Firehouse #30 (Charlotte, NC)

The data presented in this report is a record of system measurements and final adjustments that have been obtained in accordance with the current edition of the NEBB *Procedural Standards for Testing, Adjusting, and Balancing of Environmental Systems*. Any variances from design quantities, which exceed NEBB tolerances, are noted in the Test-Adjust-Balance Report Project Summary.


The air distribution system has been tested and balanced and final adjustments have been made in accordance with NEBB standards and the project specifications.

NEBB TAB FIRM: National TAB-Southeast
REGISTRATION NO: 3755
CERTIFIED BY: J. Scott Springer 23312
DATE: 9/12/2025

The hydronic distribution system has been tested and balanced and final adjustments have been made in accordance with NEBB standards and the project specifications.

NEBB TAB FIRM: National TAB-Southeast
REGISTRATION NO: 3755
CERTIFIED BY: J. Scott Springer 23312
DATE:

Submitted and Certified by:

NEBB TAB FIRM: National TAB-Southeast
TAB PROFESSIONAL: J. Scott Springer
SIGNATURE: 
REGISTRATION NO: 3755 (NTAB) / 23312
CERTIFICATION EXP: 12/31/2025

