

CheckList List

- Walgreens Survey-Exterior Pics
- Walgreens Survey-Interior Pics



08-12-24 WALGREENS #6197 DALLAS, TX (SURVEY)

CheckList Information

Name : Walgreens Survey-Exterior Pics **Status :** Not Completed
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB
Created Date : 08/14/2024 - Megan McKelvey - National TAB

CheckList Item Details

Take picture of front of building.

Comment:



08/15/2024

Picture of back of building.

Comment:



08/15/2024

Pictures of left & right side of building.

Comment:



08/15/2024



08/15/2024

Picture(s) of overall roof layout.

Comment:



08/14/2024



08/14/2024



08/14/2024



08-12-24 WALGREENS #6197 DALLAS, TX (SURVEY)

CheckList Information

Name : Walgreens Survey-Interior Pics **Status :** Completed
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB
Created Date : 08/14/2024 - Megan McKelvey - National TAB
Completed Date : 08/14/2024 - Bayley Morvant - National TAB

CheckList Item Details

Interior retail space.

Comment:



08/14/2024



08/14/2024



08/14/2024

Office area.

Comment:



08/14/2024

Picture of thermostat RTU 1. List manufacturer/model number if available.

Comment:

THERMOSTAT LOCATED IN UNIT RETURN, UNABLE TO VERIFY MANUFACTURE/MODEL NUMBER.

Picture of thermostat RTU 2. List manufacturer/model number if available.

Comment:

THERMOSTAT LOCATED IN UNIT RETURN, UNABLE TO VERIFY MANUFACTURE/MODEL NUMBER.

Picture of thermostat RTU 3. List manufacturer/model number if available.

Comment:

THERMOSTAT LOCATED IN UNIT RETURN, UNABLE TO VERIFY MANUFACTURE/MODEL NUMBER.

Picture of thermostat RTU 4. List manufacturer/model number if available.

Comment:

THERMOSTAT LOCATED IN UNIT RETURN, UNABLE TO VERIFY MANUFACTURE/MODEL NUMBER.

Picture of thermostat RTU 5. List manufacturer/model number if available.

Comment:

THERMOSTAT LOCATED IN UNIT RETURN, UNABLE TO VERIFY MANUFACTURE/MODEL NUMBER.

Stock room / storage area.


Comment:



08/14/2024

Employee breakroom (if applicable).

Comment:



08/14/2024

Above ceiling RTU 1 supply & return drop.

Comment:

UNABLE TO GET ABOVE CEILING AT THIS LOCATION TO INVESTIGATE DUCT WORK.

Above ceiling RTU 2 supply & return drop.

Comment:

UNABLE TO GET ABOVE CEILING AT THIS LOCATION TO INVESTIGATE DUCT WORK.

Above ceiling RTU 3 supply & return drop.

Comment:

UNABLE TO GET ABOVE CEILING AT THIS LOCATION TO INVESTIGATE DUCT WORK.

Above ceiling RTU 4 supply & return drop.

Comment:

UNABLE TO GET ABOVE CEILING AT THIS LOCATION TO INVESTIGATE DUCT WORK.

Above ceiling RTU 5 supply & return drop.

Comment:

UNABLE TO GET ABOVE CEILING AT THIS LOCATION TO INVESTIGATE DUCT WORK.

Ceiling of vestibule (if applicable).

Comment:

UNABLE TO GET ABOVE CEILING AT THIS LOCATION TO INVESTIGATE DUCT WORK.

Fire panel (if exists). Take picture of front of panel. If able to open panel door easily, take a picture of inside panel. List manufacturer/model number of panel if available.

Comment:



08/14/2024



08/14/2024