

# AHU-5SE GSA HQ


---

Tuesday, December 14, 2021

9 Remarks Identified



**AHU-5SE**



**NAMEPLATE**



**DAMPER POSITION**  
APPROXIMATELY 50%



**PREFILTERS**



**FINAL FILTERS**



**COOLING COIL**



**RETURN SIDE AIR DAMPER**

DOES NOT HAVE A MOTOR ATTACHED. DAMPER IS LOCKED INTO PLACE



**BELTS ARE IN GOOD CONDITION**



**OXIDATION IN THE CONDENSATE PAN**