



# CERTIFICATION

**PROJECT:** Kohls (Wesley Chapel, FL)

The data presented in this report is a record of system measurements and final adjustments that have been obtained in accordance with the current edition of the NEBB *Procedural Standards for Testing, Adjusting, and Balancing of Environmental Systems*. Any variances from design quantities, which exceed NEBB tolerances, are noted in the Test-Adjust-Balance Report Project Summary.


The air distribution system has been tested and balanced and final adjustments have been made in accordance with NEBB standards and the project specifications.

**NEBB TAB FIRM:** National TAB-Southeast  
**REGISTRATION NO:** 3755  
**CERTIFIED BY:** J. Scott Springer 23312  
**DATE:** 8/23/2024

The hydronic distribution system has been tested and balanced and final adjustments have been made in accordance with NEBB standards and the project specifications.

**NEBB TAB FIRM:** National TAB-Southeast  
**REGISTRATION NO:** 3086  
**CERTIFIED BY:** J. Scott Springer 23312  
**DATE:**

## Submitted and Certified by:

**NEBB TAB FIRM:** National TAB-Southeast  
**TAB PROFESSIONAL:** J. Scott Springer  
**SIGNATURE:**   
**REGISTRATION NO:** 3755 (NTAB) / 23312  
**CERTIFICATION EXP:** 12/31/2024

