

## CheckList List

- WALGREENS SURVEY - RTU # 3



**Comment:**



**08/19/2024**

**Right side of cabinet.**

**Comment:**



**08/19/2024**

**Front side of cabinet.**

**Comment:**



08/19/2024

---

**Back side of cabinet.**

**Comment:**

---



08/19/2024

---

**Inside of electrical cabinet.**

**Comment:**

---



08/19/2024

---

**Electrical schematic.**

**Comment:**




08/19/2024

---

**Close up picture of condensing coil.**

**Comment:**



08/19/2024

---

**Blower compartment.**

**Comment:**



08/19/2024

---

**Mixed air compartment.**

**Comment:**



08/19/2024

Close up of evaporative coil.

Comment:



08/19/2024

Return drop looking down from unit if possible.

Comment:




08/19/2024

---

Supply drop looking down from unit if possible.

Comment:



08/19/2024

---

List any visual damage and take additional pictures if needed.

Comment:

---