

CheckList List

- WALGREENS SURVEY - RTU # 6


Comment:



08/19/2024

Right side of cabinet.


Comment:



08/19/2024

Front side of cabinet.

Comment:



08/19/2024

Back side of cabinet.

Comment:



08/19/2024


Inside of electrical cabinet.

Comment:




Electrical schematic.

Comment:



Close up picture of condensing coil.


Comment:



08/19/2024

Blower compartment.

Comment:



08/19/2024

Mixed air compartment.


Comment:



08/19/2024

Close up of evaporative coil.

Comment:



08/19/2024

Return drop looking down from unit if possible.

Comment:



08/19/2024

Supply drop looking down from unit if possible.

Comment:



08/19/2024

List any visual damage and take additional pictures if needed.

Comment: