

## CheckList List

- WALGREENS SURVEY - ELECTRICAL PANEL # 1
- WALGREENS SURVEY - ENTRANCE HEATER



**08-26-24 WALGREENS #17587 BALTIMORE, MD (SURVEY)**


**CheckList Information**

**Name :** WALGREENS SURVEY - ELECTRICAL PANEL # 1      **Status :** Completed  
**Assigned Organization :** National TAB      **Asset :**  
**Requesting Organization :** National TAB  
**Created Date :** 08/22/2024 - Brianna Biggs - National TAB  
**Completed Date :** 08/28/2024 - David Annan - National TAB

**CheckList Item Details**

**Unit label or markings. Picture of front of panel.**

**Comment:**



**08/28/2024**

**Open the panel door and take picture of all the breakers and a picture of the inside door panel where label / information is applied.**

**Comment:**



**Size and type of RTU unit breaker 4.**

**Comment:**

**Size and type of RTU unit breaker 5.**

**Comment:**

**Size and type of exhaust fan #1 breaker.**

**Comment:**

20 A breaker

**Size and type of exhaust fan #2 breaker.**

**Comment:**

20 A breaker

**Size and type of exhaust fan #3 breaker.**

**Comment:**

**Size and type of exhaust fan #4 breaker.**

**Comment:**



08-26-24 WALGREENS #17587 BALTIMORE, MD (SURVEY)

CheckList Information

**Name :** WALGREENS SURVEY - ENTRANCE HEATER      **Status :** Completed

**Assigned Organization :** National TAB      **Asset :**

**Requesting Organization :** National TAB

**Created Date :** 08/22/2024 - Brianna Biggs - National TAB

**Completed Date :** 08/28/2024 - David Annan - National TAB

CheckList Item Details

List unit label or tag nomenclature (if exists).

**Comment:**

There is no heater at this location

Close up picture of unit tag.

**Comment:**

There is no heater at this location

List model serial number & manufacturer.

**Comment:**

There is no heater at this location

Left side of cabinet.

**Comment:**

There is no heater at this location

Right side of cabinet.

**Comment:**

There is no heater at this location

Front side of cabinet.

**Comment:**

There is no heater at this location

---

**Back side of cabinet.**

**Comment:**

There is no heater at this location

---

**Inside of electrical cabinet.**

**Comment:**

There is no heater at this location

---

**Electrical schematic.**

**Comment:**

There is no heater at this location

---

**Close up picture of condensing coil.**

**Comment:**

There is no heater at this location

---

**Blower compartment.**

**Comment:**

There is no heater at this location

---

**Mixed air compartment.**

**Comment:**

There is no heater at this location

---

**Close up of evaporative coil.**

**Comment:**

There is no heater at this location

---

**Return drop looking down from unit if possible.**

**Comment:**

There is no heater at this location

---

**Supply drop looking down from unit if possible.**

**Comment:**

There is no heater at this location

---

List any visual damage and take additional pictures if needed.

Comment: