

PlanGrid Task Report - Jan 29, 2025

Prepared by Stephen Tassinaro

Jan 29, 2025

Description

2 tasks in this report.

Contents

#127 [SITE 500] [NEW] TAB is complete.	2
#73 [EXHA 508] [NEW] Exhaust fan G2 Drip Guard.	3

L05792_North Platte FSU (NE)

1902 South Jeffers Street, North Platte, Nebraska

L1020005792

#127 [SITE 500] [NEW] TAB is complete.

Status

Open

Start Date

Jan 29, 2025

Type

Planned Work

Created

Jan 29, 2025 1:39 PM
stephent@nationaltab.com

Description

TAB is complete with only non-critical tasks open or all critical/non-critical tasks closed.

Last Updated

Jan 29, 2025 1:39 PM

L05792_North Platte FSU (NE)

1902 South Jeffers Street, North Platte, Nebraska

L1020005792

#73 [EXHA 508] [NEW] Exhaust fan G2 Drip Guard.

Status

Open

Assignees

rodc@deansnyder.com

Sheet

M-501

Type

Planned Work

Watchers

rodc@deansnyder.com

List

Turnover

Start Date

Jan 7, 2025

Description


Exhaust fan G2 Drip Guard is missing.

Created

Jan 7, 2025 5:41 PM
jacobd@nationaltab.com

Last Updated

Jan 29, 2025 1:38 PM



Comments

Extend drain to center of drip guard as per M501 to close issue.

Stephen Tassinaro Jan 29, 2025

Photos

L05792_North Platte FSU (NE)

1902 South Jeffers Street, North Platte, Nebraska

L1020005792



Resized_20250115_100226_1736970221099

Jared Locke

Jan 15, 2025 4:58 PM



Resized_20250115_094946_1736970222241

Jared Locke

Jan 15, 2025 4:58 PM



IMG_0578

Jacob Davidson

Jan 7, 2025 5:43 PM



IMG_0577

Jacob Davidson

Jan 7, 2025 5:43 PM