

CheckList List

- WALGREENS SURVEY - EF # 1
- WALGREENS SURVEY - EF # 2
- WALGREENS SURVEY - EF # 3



08-26-24 WALGREENS #19336 LARGO, MD (SURVEY)

CheckList Information

Name : WALGREENS SURVEY - EF # 1 **Status :** Completed

Assigned Organization : National TAB **Asset :**

Requesting Organization : National TAB

Created Date : 08/27/2024 - Brianna Biggs - National TAB

Completed Date : 08/27/2024 - David Annan - National TAB

CheckList Item Details

Unit label or markings if any.

Comment:

Unit is not accessible

Unit tag manufacturer, model number, and serial number.

Comment:

Unit is not accessible

Interior fan picture (motor / disconnect compartment under fan cap).

Comment:

Unit is not accessible

Picture of curb. Measure length and width of curb.

Comment:

Fan is not on the roof.

Does fan spin freely?

Comment:

Unit is not accessible

List any visual damage and take additional pictures if needed.

Comment:

Unit is not accessible



08-26-24 WALGREENS #19336 LARGO, MD (SURVEY)

CheckList Information

Name : WALGREENS SURVEY - EF # 2 **Status :** Completed
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB
Created Date : 08/27/2024 - Brianna Biggs - National TAB
Completed Date : 08/27/2024 - David Annan - National TAB

CheckList Item Details

Unit label or markings if any.

Comment:

Unit is not accessible

Unit tag manufacturer, model number, and serial number.

Comment:

Unit is not accessible

Interior fan picture (motor / disconnect compartment under fan cap).

Comment:

Unit is not accessible

Picture of curb. Measure length and width of curb.

Comment:

Fan is not on the roof

Does fan spin freely?

Comment:

Unit is not accessible

List any visual damage and take additional pictures if needed.

Comment:

Unit is not accessible

