





Comfort. Under control.

## 02-20-23 LIVERY - MONTGOMERY, OH

### Project Issue Information

**Issue Name :** MUA plenum

**Description :** The main left hood plenum box is open to the space, need to attach flex duct for balancing. Dish hood does not have any ductwork attached to plenum box. Fourstar said email stated that they didn't need to run any make up air over to the space.

**Created By :** National TAB

**Assigned To :** National TAB - Joe Hertenstein

**Status :** Open

**Originated Date :** 02/20/2023 - Austin McFall - National TAB