

**Report By:**

**National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246**



**Report: DALT 6-29 Garden Level  
Function: Test, Adjust, & Balance  
Date: 06/29/2023**

**PROJECT**  
**Westover Hills (San Antonio, TX)**

3011 W Loop 1604 N

San Antonio, TX

**Client**

Robins & Morton  
2015 Ayrley Town Blvd Suite 203  
Charlotte, NC 28273

# National TAB

Project: Westover Hills (San Antonio, TX)

## Table Of Contents

Section	Page #
DALT Garden Level 6-29	3



**NATIONAL TAB**  
AIR DUCT LEAKAGE TEST SUMMARY



Comfort. Under control.

Tested: 6/29/2023

PROJECT: Westover Hills Baptist Hospital, San Antonio, TX  
 ASSET: AHU G-1  
 LEAKAGE CLASS 4  
 SPECIFIED TEST PRESSURE (P<sub>i</sub>) 6"  
 DUCT CONSTRUCTION PRESSURE CLASS (P<sub>c</sub>) A

DESIGN DATA				FIELD TEST DATA RECORD						
SUBJECT DUCT	SURFACE AREA IN FT <sup>2</sup>	ALLOWABLE LEAKAGE		DIAMETER		PRESSURE " W.G.	DATE	PERFORMED BY	WITNESSED BY	ACTUAL CFM
		LIMIT	CFM	ORIFICE	TUBE					
			(TEST SECTION)			DUCT				
<b>SUPPLY DUCT</b>										
1	1188	0.096	114.05	3.75	4	6.08	6/29/2023	WJ	Charles Eubanks	68.55
	<b>1188</b>		<b>114.05</b>							<b>68.55</b>

REMARKS

TAB TEAM: National TAB  
 CONSTRUCTION TEAM: Robins & Morton

DATE: 6/29/2023



**NATIONAL TAB**  
AIR DUCT LEAKAGE TEST SUMMARY



Comfort. Under control.

Tested: 6/29/2023

PROJECT: Westover Hills Baptist Hospital, San Antonio, TX  
 ASSET: AHU G-1  
 LEAKAGE CLASS 6  
 SPECIFIED TEST PRESSURE (Pi) 2"  
 DUCT CONSTRUCTION PRESSURE CLASS (Pc) C

DESIGN DATA				FIELD TEST DATA RECORD						
SUBJECT DUCT	SURFACE AREA IN FT <sup>2</sup>	ALLOWABLE LEAKAGE		DIAMETER		PRESSURE " W.G.	DATE	PERFORMED BY	WITNESSED BY	ACTUAL CFM
		LIMIT	CFM	ORIFICE	TUBE	DUCT				
			(TEST SECTION)							
<b>RETURN DUCT</b>										
1	1078	0.094	101.33	3.75	4	2.086	6/29/2023	WJ	Charles Eubanks	41.34
	<b>1078</b>		<b>101.33</b>							<b>41.34</b>

REMARKS

TAB TEAM: National TAB  
 CONSTRUCTION TEAM: Robins & Morton

DATE: 6/29/2023





Comfort. Under control.

NATIONAL TAB  
AIR DUCT LEAKAGE TEST SUMMARY



Tested: 6/29/2023

PROJECT: Westover Hills Baptist Hospital, San Antonio, TX

ASSET: EXHAUST Garden Level

LEAKAGE CLASS 6

SPECIFIED TEST PRESSURE (Pi) 2"

DUCT CONSTRUCTION PRESSURE CLASS (Pc) C

DESIGN DATA				FIELD TEST DATA RECORD						
SUBJECT DUCT	SURFACE AREA IN FT <sup>2</sup>	ALLOWABLE LEAKAGE		DIAMETER		PRESSURE " W.G.		PERFORMED BY	WITNESSED BY	ACTUAL CFM
		LIMIT	CFM	ORIFICE	TUBE	DUCT	DATE			
			(TEST SECTION)							
<b>EXHAUST DUCT</b>										
2	725	0.094	68.15	3.75	4	2.111	6/29/2023	WJ	Charles Eubanks	49.14
	<b>725</b>		<b>68.15</b>							<b>49.14</b>

REMARKS

TAB TEAM: National TAB  
CONSTRUCTION TEAM: Robins & Morton

DATE: 6/29/2023