

Shell Station (Cincinnati)

Project Issue Information

Issue Name :	wall steel	Organization :	Teegarden HVAC
Status :	Open	Assigned To :	Air Solutions, Inc - Joe Hertenstein
Shared To :	Jim Cirlli,Joe Hertenstein,Austin Mcfall,	Created :	Dave Turner
Open :	09/24/2021 - Dave Turner - Teegarden HVAC	Description:	Right side wall piece is 48" Wall is 40"

Project Issue Response Details

- **09/24/2021** **Air Solutions, Inc - Austin Mcfall**
 - Dave, i thought the wall was 50", not 40". If it indeed 40" you'll need to cut it with a metal saw.