



Project Summary

SCOPE OF WORK:

Our focus for this project was to evaluate the existing facility for the following:

- Measure all exhaust fans airflow, amps, and volts and evaluate the condition
- Provide an as-built sketch of the ductwork in the space and gather specific dimensions requested from the engineer of record.

Finally provide any additional insight about the facility or its Mechanical assets that will allow the maintenance & design teams determine best direction for future repairs, replacement, or modifications.

CONTENT OF ENCLOSED REPORT:

The following pages include issues and recommendations from the assets that were reviewed. After those pages are checklists with pictures and descriptions of inspections that were performed. Last are asset pages with results from the airflow and performance testing.