

Summary

Project: Formica Preliminary Report (Cincinnati, OH)

Included in this report are Fan Coil Units (FCUs) and (ERV) readings for floors 3- through floor 12. This is a partial report while TAB is in progress on the remaining floors. Once TAB is complete a final summary will be written encompassing all scope of work, processes used to achieve design flows, and action taken to correct issues. A final GRD and TOC will also be included.