

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: TAB PUNCLIST
Function: Test, Adjust, & Balance
Date: 06/03/2025
Completed By: National TAB

PROJECT

**06-02-25 CAVA NORTH BRUNSWICK, NJ
(MAIN ST)**

222 GRAND AVE

NORTH BRUNSWICK TOWNSHIP, NJ 08902

Client

CAVA
702 H ST NW
2nd floor
Washington, DC 20001

National TAB

Project: 06-02-25 CAVA NORTH BRUNSWICK, NJ (MAIN ST)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- RTU- Filters
- RTU-1 Compressors
- RTUs Missing hail guards



06-02-25 CAVA NORTH BRUNSWICK, NJ (MAIN ST)

Project Issue Information

Issue Name : RTU- Filters
Description : RTU filters are still construction type. Needs to be swapped to MERV 8 filters prior to turnover.
Created By : National TAB **Assigned To :** National TAB - Tyler Youells
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 06/03/2025 - Tyler Youells - National TAB



06-02-25 CAVA NORTH BRUNSWICK, NJ (MAIN ST)

Project Issue Information

Issue Name : RTU-1 Compressors
Description : RTU-1 compressors do not sound healthy, could be incorrect rotation. Recommend MC diagnose.
Created By : National TAB **Assigned To :** National TAB - Tyler Youells
Status : Open
Priority : High **Asset Tag :**
Originated Date : 06/03/2025 - Tyler Youells - National TAB



06-02-25 CAVA NORTH BRUNSWICK, NJ (MAIN ST)

Project Issue Information

Issue Name : RTUs Missing hail guards
Description : See M400 RTU remarks section
Created By : National TAB **Assigned To :** National TAB - Tyler Youells
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 06/03/2025 - Tyler Youells - National TAB


Project Issue File Details



06/03/2025



06/03/2025



06/03/2025