



Comfort. Under control.

10-31 FREDDY'S - OVERLAND PARK, KS (135TH) - RENEW 2B (5)

CheckList Information

Name : RENEW - SITE PICTURES **Status :** Submitted
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB

CheckList Item Details

ROOF TOP BEFORE AND AFTER PICTURES

RTU 1 O.A. MESH FILTER (BEFORE AND AFTER)

No OA FILTER



NoOAFilter.jpeg

RTU 1 FINAL FILTER (BEFORE AND AFTER)



Clean.jpeg



Diety.jpeg

RTU 1 CONDENSER COIL (BEFORE AND AFTER)



Clean.jpeg



Dirty(1).jpeg

RTU 1 EVAPORATOR COIL (BEFORE AND AFTER)



Dirty(1).jpeg



Clean.jpeg

RTU 1 - CONDENSATE DRAIN



Drain.jpeg

RTU 1 CONDENSATE PAN



Pan.jpeg

RTU 1 COMBUSITION FAN AND BURNER
CONTROLS COMPARTMENT



Clean.jpeg



Dirty(1).jpeg

RTU 1 HEAT EXCHANGER



Heattubes.jpeg

RTU 2 OA FILTER (BEFORE AND AFTER)



Clean.jpeg



Dirty(1).jpeg



Cakedindirty.jpeg

RTU 2 FINAL FILTER (BEFORE AND AFTER)



Clean.jpeg



Dirty(1).jpeg

RTU 2 CONDENSER COIL (BEFORE AND AFTER)



Clean.jpeg



Dirty(1).jpeg

RTU 2 EVAPORATOR COIL (BEFORE AND AFTER)



Clean.jpeg



Dirty(1).jpeg

RTU 2 CONDENSATE DRAIN



Drain.jpeg

RTU 2 CONDENSATE PAN



Pan.jpeg



Dirty(1).jpeg

RTU 2 COMBUSTION FAN AND BURNER
CONTROLS COMPARTMENT



Dirty(1).jpeg



Cleaned.jpeg

RTU 2 HEAT EXCHANGER



Heattubes.jpeg

RTU 3 OA MESH FILTER (BEFORE AND AFTER)

SAT ON THE ROOF FOR A LONG TIME NEED EXTRA ATTENTION AT NEXT RENEW



Dirty(1).jpeg



Clean.jpeg



Dirty(1).jpeg

RTU 3 FINAL FILTER (BEFORE AND AFTER)



Clean.jpeg



Dirty(1).jpeg

RTU 3 CONDENSER COIL (BEFORE AND AFTER)



Dirtyfromcoils.jpeg



Dirty(1).jpeg



Clean.jpeg

RTU 3 EVAPORATOR COIL (BEFORE AND AFTER)



Clean.jpeg



Dirty(1).jpeg

RTU 3 CONDENSATE DRAIN



Drain.jpeg

RTU 3 CONDENSATE PAN



Pan.jpeg

**RTU 3 COMBUSTION FAN AND BURNER
CONTROLS COMPARTMENT**



Dirty(1).jpeg



Dirty(1).jpeg

RTU 3 HEAT EXCHANGER



Burnertubes.jpeg

MUA FAN BEFORE AND AFTER PICTURES

MUA OA MESH FILTERS



Clean.jpeg



Dirty(1).jpeg

MUA BLOWER/MOTOR COMPARTMENT



BlowerMotor.jpeg

MUA HEATER CONTROLS COMPARTMENT



Controls.jpeg

MUA DX COIL, CONDENSATE PAN, AND DRAIN (IF UNIT HAS ONE) NA

EXHAUST FAN BEFORE AND AFTER PICTURES

EXHAUST FAN KEF1 MOTOR HOUSING CLEANED

EXHAUST FAN KEF1 GREASE CUP PROPERLY INSTALLED

EXHAUST FAN KEF2 MOTOR HOUSING CLEANED Did not have time to clean

EXHAUST FAN KEF2 GREASE CUP PROPERLY INSTALLED



Installed.jpeg

EXHAUST FAN KEF3 MOTOR HOUSING CLEANED NA

EF-1 RESTROOMS FAN HOUSING PICTURE 101CFM



MENSRR.jpeg

EF-2 RESTROOMS FAN HOUSING PICTURE


69CFM



WOMENSRR.jpeg

FINAL BUILDING PERFORMANCE


ADD PHOTO OF THE FINAL PRESSURE TAKEN WITH YOUR METER AT THE FRONT AND BACK KITCHEN DOOR



Side.jpeg



Front.jpeg



Back.jpeg

ADD SHORT VIDEO OF HOOD CAPTURE WHILE COOKING OR WITH SMOKE CANDLE

SEE HOOD CAPTURE ON OTHER CHECKLIST

COILS

DXC1

WALK-IN COOLER



Clean.jpeg



Dirty(1).jpeg

DXC2

WALK IN FREEZER



Dirty(1).jpeg



Clean.jpeg

DXC3

MEAT COOLER



Dirty(1).jpeg



Clean.jpeg

DXC4

MEAT COOLER 2



Clean.jpeg



Dirty(1).jpeg

DXC5

Prep station



Dirty(1).jpeg



Clean.jpeg

DXC6

PREP STATION



Dirty(1).jpeg



Clean.jpeg

DXC7

FRYER FREEZER



Dirty(1).jpeg



Clean.jpeg

DXC8

REACH IN FREEZER



Clean.jpeg



Dirty(1).jpeg

Notes/Comments :