

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Notes

Function: Test, Adjust, & Balance

Date: 11/08/2024

Completed By: National TAB

PROJECT
USACE HVAC Reset (Palatka, FL)

4300 St. Johns Avenue

Palatka, FL _____

Client

TEAM CONSTRUCTION

825 GUM BRANCH RD

STE 128

JACKSONVILLE, NC 28540

National TAB

Project: USACE HVAC Reset (Palatka, FL)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- Project Notes

USACE HVAC Reset (Palatka, FL)

Project Issue Information

Issue Name : Project Notes

Description : • FCU-8 next steps are just balance diffusers once face accessible dampers are installed. • Women's RR EF (EF-2) - total was roughly set with no diffusers installed. Will rebalance once everything is 100% installed. There was not a 100% seal from the ductwork to the hood due to the lack of diffusers. • PAL02-EF-2 - See attachments. • MAU-2 does no


Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert

Status : Open

Priority : InfoOnly **Asset Tag :**

Originated Date : 11/08/2024 - Stephan Gabbert - National TAB

Project Issue File Details



11/08/2024



11/08/2024