



### 03-10-25 POPUP EVAL #338 NY, NY (COLUMBUS)

#### CheckList Information

**Name :** Site Evaluation Pictures      **Status :** Not Completed

**Assigned Organization :** National TAB      **Asset :**

**Requesting Organization :** National TAB

**Created Date :** 03/13/2025 - Joe Hertenstein - National TAB

#### CheckList Item Details

BELOW IS A VISUAL INSPECTION OF SPACE & ANY ASSETS IN SPACE

Picture of Front outside store front

**Comment:**



03/13/2025



03/13/2025

After entering, get a picture or two of the space. This provides a full view & understanding of the setup. So, zoom out to get as much as possible

**Comment:**



03/13/2025



03/13/2025

picture of the oven area & boiling pot area

**Comment:**



03/13/2025



03/13/2025

picture of the exterior louvers outside where each exhaust & outside air is provided

**Comment:**



03/13/2025



03/13/2025



03/13/2025

Go to electrical breaker panel(s) for the space & take picture of front of panel, then open door & take picture of breakers & then the inside cover of the door (tags)

**Comment:**



03/13/2025



03/13/2025



03/13/2025

Pictures of AHU Unit

**Comment:**



03/13/2025



03/13/2025



03/13/2025

Picture of hood exhaust fan

Comment:



03/13/2025



03/13/2025

Picture of Outside air Fan

Comment:



03/13/2025



03/13/2025



03/13/2025

Picture of Scrubber (Odor Control Unit) between hood & fan.

**Comment:**



**03/13/2025**



**03/13/2025**