

CheckList List

- WALGREENS SURVEY - RTU # 2



08-26-24 WALGREENS #18155 BALTIMORE, MD (SURVEY)

CheckList Information

Name : WALGREENS SURVEY - RTU # 2 **Status :** Completed
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB
Created Date : 08/22/2024 - Brianna Biggs - National TAB
Completed Date : 09/10/2024 - David Annan - National TAB

CheckList Item Details

List unit label or tag nomenclature (if exists).

Comment:



09/10/2024

Close up picture of unit tag.

Comment:



09/10/2024

List model serial number & manufacturer.

Comment:

YORK Model: DF090N15N2AAA4B Serial: N0E887030

Left side of cabinet.

Comment:



09/10/2024

Right side of cabinet.

Comment:



09/10/2024

Front side of cabinet.

Comment:



09/10/2024

Back side of cabinet.


Comment:



09/10/2024

Inside of electrical cabinet.


Comment:




09/10/2024

Electrical schematic.

Comment:




09/10/2024



09/10/2024

Close up picture of condensing coil.

Comment:




09/10/2024



09/10/2024

Blower compartment.

Comment:



09/10/2024

Mixed air compartment.

Comment:



09/10/2024

Close up of evaporative coil.

Comment:



09/10/2024



09/10/2024

Return drop looking down from unit if possible.

Comment:

Unable to access the return duct internally



09/10/2024

Supply drop looking down from unit if possible.

Comment:



09/10/2024

List any visual damage and take additional pictures if needed.

Comment:

Dirty filters. Dirty Evaporator coils.
