

CHIPOTLE BRISTOL TN

Wednesday, June 22, 2022

9 Issues Identified



GENERAL

Assigned To EF1

Unit picture



GENERAL

Assigned To EF2

Unit picture



GENERAL

Assigned To MAU

Unit picture



GENERAL

Assigned To RTU1

Unit picture



GENERAL

Assigned To RTU2

Unit picture



GENERAL

Assigned To HD
Unit picture



GENERAL

Assigned To HD
Grease duct above hood



GENERAL

Assigned To RTUs
Gridpoint system installed



GENERAL

Assigned To Store
Front of store.