



Comfort. Under control.

07-11 CULVERS - ELLISVILLE, MO

**Project Issue Information**

**Issue Name :** HD1 ANSUL pipe preventing filter placement  
**Description :** ANSUL PIPE is preventing second layer filter from being put in place. Cannot balance hood.  
**Created By :** National TAB **Assigned To :** National TAB - Will Turnbough  
**Status :** Closed  
**Originated Date :** 07/11/2022 - Jacob Davidson - National TAB

Project Issue File Details



FuseITe0bc91a48e034d4abc  
bbf4fe10d69cc5.jpeg



FuseITac7533c5eace4f608ed  
8d3da11d5a97b.jpeg

Project Issue Response Details

- 07/13/2022 National TAB - Jacob Davidson
  - The pipe has been rotated and the filters are all installed in the hood



FuseIT7113922c3579420  
98281d69654b5c6aa.jpe  
g